
# 

Desk



TOOLS REQUIRED
POZIDRIVE SCREW DRIVER

DESK COMPONENTS	QUANTITY
TOP	1
LEFT LEG	1
RIGHT LEG	1
BRACE	1
HARDWARE	QUANTITY
( PACKAGED WITH LEGS )	
CAMS (PRE FITTED IN FACTORY )	13
CAM BOLTS	13

#### STEP 1

PLACE TOP PANEL FACE DOWN ON A CLEAN SURFACE SUCH AS CARPET ENSURING THERE IS NO DIRT OR GRIT THAT MAY CAUSE SCRATCHES.

## STEP 2

USING A POZIDRIVE SCREWDRIVER INSERT 9 CAM BOLTS INTO THE 5MM DRILLED HOLES IN THE TOPS

# STEP 3

USING A POZIDRIVE SCREWDRIVER INSERT 2 CAM BOLTS INTO THE 5MM DRILLED HOLES IN THE LEFT HAND LEG

# STEP 4

USING A POZIDRIVE SCREWDRIVER INSERT 2 CAM BOLTS INTO THE 5MM DRILLED HOLES IN THE RIGHT HAND LEG

### STEP 5

PLACE THE LEFT HAND LEG PANEL AND CAMS ON TO THE TOP CAM BOLTS AND USING A POZIDRIVE SCREWDRIVER TIGHTEN CAMS UNTIL FULLY TIGHT

#### STEP 6

PLACE THE BRACE PANEL AND CAMS ON TO THE TOP AND LEG PANEL CAM BOLTS AND USING A POZIDRIVE SCREWDRIVER TIGHTEN CAMS UNTIL FULLY TIGHT

## STEP 7

PLACE THE RIGHT HAND LEG PANEL AND CAMS ON TO THE TOP CAM BOLTS AND USING A POZIDRIVE SCREWDRIVER TIGHTEN CAMS UNTIL FULLY TIGHT

#### STEP 8

BEFORE TURNING THE DESK THE CORRECT WAY UP, PLEASE ENSURE ALL CAMS ARE FULLY TIGHTENED

## STEP 9

USING A 2ND PERSON TO HELP LIFT, TURN THE DESK OVER AND PLACE IN DESIRED POSITION, DO NOT DRAG ASSEMBLED DESK

YOU ARE NOW READY TO ENJOY YOUR DESK. THANK YOU, WE APPRECIATE YOU SUPPORTING OUR NEW ZEALAND MADE PRODUCT