



PARTS




①




M6X70 X4

②




M6X25 X4

③




X4



IMPORTANT: DON'T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.

1



2

